

**1 Products affected**

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU Type				
04	019	200	0000008801	4435.XXXX	Circuit Protection	TA35 rocker type 1-pole
04	019	200	0000008802	4435.XXXX	Circuit Protection	TA35 rocker type 2-pole*
04	019	200	0000008803	4435.XXXX	Circuit Protection	TA35 rocker type 3-pole
04	019	202	0000008821	4435.XXXX	Circuit Protection	TA35 rotary knob 1-pole
04	019	202	0000008822	4435.XXXX	Circuit Protection	TA35 rotary knob 2-pole
04	019	202	0000008823	4435.XXXX	Circuit Protection	TA35 rotary knob 3-pole

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

\*Exception: 4435.0689; 4435.0690; 4435.0691; 4435.0702; 4435.0707

**2 Type of change**

Product Improvement. CCC approval mark added.

**3 Detailed description of change**

CCC approval mark added on the product label and all approval marks are added on the packaging label.

Product label:

old	new

Packaging label:

old	new

TA35					0118.2171	
creation date	created by	release date	released by	notification no.	revision	page
2013-04-26	buholzma	2013-06-19	buholzma	24696	-	1 of 2

#### 4 Reason of change

CCC approval for TA35.

#### 5 Released date

The change will be rolled-out ww 18/2013 and lasts approx. 6 months.

#### 6 Impact of change and recommended action

Form: N/A  
Fit: N/A  
Function: N/A  
Production Site: N/A  
Product Label: New CCC approval marking

TA35					0118.2171	
creation date	created by	release date	released by	notification no.	revision	page
2013-04-26	buholzma	2013-06-19	buholzma	24696	-	2 of 2