

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type Description	Customer part no.
SBU	PG	PGU	Type				
02	005	115	0000001137	CMF1.XXXX.XX	Power Entry Modules w/o Filter	CMF1	
02	005	115	0000001138	CMF2.XXXX.XX	Power Entry Modules w/o Filter	CMF2	
02	005	115	0000001139	CMF3.XXXX.XX	Power Entry Modules w/o Filter	CMF3	
02	005	115	0000001137	CMF4.XXXX.XX	Power Entry Modules w/o Filter	CMF4	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)


2 Type of change

Modification of approval marks


Detailed description of change

New CCC approval mark is on the CMF body.
In the picture a CMF1 type as an example for all CMF types.

Old marking:



New marking



3 Reason of change

Chinese approval

4 Released date

Release for series production

Ww19/2012

5 Impact of change and recommended action

Form: New approval
Fit: N/A
Function: N/A
Production Site: Change of tool
Product label: N/A

6 Reference Documents / Attachments

Kind of document	Document number	Remarks
Notification of change	22957	

CMF					0118.2107	
creation date	created by	release date	released by	notification no.	revision	page
2012-05-25	ros	2012-08-03	ros	23568	-	1 of 1